

Communication Issue with Fiery Icon and MFP

SP 5305-101 to "0"

User Tools

System Settings

Administrator Tools

Page 3-5

Sleep Mode Entry By Sleep Mode Time to "disable"

SP 5191-001 Mode Set to "0"

Reboot Machine