We were discussing this issue in class and actually found that the 6002 does have a drum heater that can be activated by plugging it in. See manual...

Going forward All drum heaters need to be plugged in on next service call.

**This should correct the blurry drum issue.

Please do so on the next call you have on these models.

