

Problem: D3AZ & DEB0 single pass jam 63 fix

Solution: Ricoh has released a FW update for the above SPDFs that is supposed to limit the amount of jam 63 codes.

In RFG you can find the FW for each feeder

D3AZ  
rfg071943

D3B0  
rfg071620