

Potential problem with the newest versions of the Ricoh 8300.
Problem Intermittent SC563

Found that the wire ties are too tight on thermistor wiring breaking the wire (See Pics)
Part # to correct the issue is D1795381
This part is the harness that includes thermistor and heat sensors for Upper fuser unit...



