

C4504ex with a Document feeder issue.

It was a jam no jam in feeder or intermittent sc700-02.

It has the single pass feeder, D3B0, on it.

It was the pickup cam stepper motor, replaced it now all it well.

Part #D6831675

Part was hard to find in parts Manual.

Be on the lookout for this issue.