

Just had an issue with a MP5054 machine that was jamming at the vertical transport (J051 and J052) area along with loud noise from vertical transport motor. The fix was replacement of the BCU. These are fairly new machines in the field and this might help others if they see the problem..

NOTE: After replacing the BCU it will give a SC995 at Power Up..they will need to re enter the machines correct S/N back in with SP5811-004