

Machine that would show a J174 when corner stapling. When he tried to double staple the rear staple would not clinch.

The problem was the rear fence was out of synch with the front fence, causing the fence guide to be in between the stapler jaws, blocking the clincher.

He solved the problem by synchronizing the fences.