

Tech tip for Ricoh Color machines.

Performing a fresh ACC adjustment the correct way!

Should be done on Low - Mid Volume Ricoh color machines. Do not perform on Production machines with Fiery Controllers. These customers typically perform Fiery color calibrations themselves.

When to do this:

On every visit after service has been performed and before Line Alignments are adjusted.

Procedure:

Clear the previous ACC calibrations using SP 5-610-4

This wipes all previous calibrations and restores your machine back to its original color state. It may also may correct a line alignment issue.

Now you can properly perform the ACC procedure in user tools.

Note: Do not Force Toner to correct a light copy quality condition. Using the above procedure will correct most color density issues.