

## SC400 on a MPC 401 and 300.

Machine will show SC400 and the fix is that the ID Sensor Shutter is probably hanging up and not opening completely.

Heat from the fusers can deform the plastic on the upper half of the shutter and cause it to not open/close properly.