

Firmware update causing problems (machine freeze) on MP301

The firmware update causing problems (machine freeze) is the, System 9/29/2017 D127-D128_System_v3.24_SDcard.

When you go to:

User Tools/Counter, System Settings, Interface Settings, and touch the Network (to change the IP address, etc.), the machine freeze.