C550/451/353 EMPERON IP SETTINGS WITH A FIERY CONTROLLER

IP of the Engine should be set as a STATIC IP and not DHCP
This address is only used by the Fiery to communicate with the engine.

