

MFP 3054, Document Feeder issue...updates Document Feeder firmware, firmware history list J14 and j16 errors specifically. She was have issues especially with checks (8.5x11), updated firmware and increased paper buckle to 2mm, jamming seems so have been corrected, scanned a stack of checks. Jammed multi times prior to adjustment, added 2mm of buckle, jamming has ceased since. Seems to be ok, advised to call if any issues.