MP5055 JO21

Paper stops approximately .25 inch onto bridge transport. The paper support guide, which attaches to the exit of the copier, was

in place but not locked down.

